


Beware!


Counterfeit Timing Belt Tensioner

Litens Automotive would like to advise Distributors, Jobbers, Retailers, and Installers of **counterfeit timing belt tensioners** being sold throughout the Mexican market.

As the original equipment supplier of this part, Litens would like to warn the industry that this counterfeit product has not been produced with the correct materials or the correct specifications for the applications intended. Installation of the counterfeit part may cause severe engine damage and is a potential consumer safety concern.



The counterfeiter has gone to great efforts to deceive the automotive aftermarket by copying the OE part numbers, manufacturer's logo, as well as the country of origin. This fake is produced to look exactly like the Original Equipment part available from GM dealers.



Litens' current aftermarket part has the number 979111 stamped on the back plate and has been made to exact original equipment specifications.



To protect your vehicle and reputation, please purchase your genuine service parts directly from the original equipment dealership and your aftermarket parts (979111) from an authorized Litens aftermarket parts supplier.

Original Equipment Numbers for this Tensioner Include:
9202478; 90499401; 90353176; 90353176; 90354783; 90499401
90570525; 5636721; 5636722; 636734; 636740; 636748; 636749

Application: Opel / Daewoo / Leganza / GM
Model Years 1990 & 1998-03
Family 1 Engines: 1.2L / 1.4L / 1.5L / 1.6 SOHC

Please Note: It is against the law to produce, distribute, or buy counterfeit parts. In order to protect our good name, Litens Automotive will do everything possible to press legal action against any and all companies that participate in the distribution and use of this potentially dangerous product.